

FIG. 1A

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 2/27




FIG. 1B




FIG. 2A

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 4/27




FIG. 2B

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 5/27




FIG. 2C

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 6/27




FIG. 2D

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 7/27




FIG. 2E

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 8/27




FIG. 2F

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 9/27




FIG. 2G

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 10/27

Transmit

in A

vividamente

ff

Saxophone Clarinet Flute Trumpet Trombone

G# Scroll Select

FIG. 3

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 11/27




FIG. 4

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 12/27




FIG. 5

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 13/27




FIG. 6

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 14/27




FIG. 7

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 15/27




FIG. 8

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 16/27




FIG. 9

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 17/27




FIG. 10

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 18/27




FIG. 11A

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 19/27




FIG. 11B

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 20/27




FIG. 12

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 21/27




FIG. 13

DAVID H. SITRICK
 STD 1757
 REPLACEMENT SHEET 22/27




FIG. 14

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 23/27





FIG. 15

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 24/27




FIG. 16

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 25/27




FIG. 17

DAVID H. SITRICK
 STD 1757
 REPLACEMENT SHEET 26/27





FIG. 18

DAVID H. SITRICK
STD 1757
REPLACEMENT SHEET 27/27

Master Station Buffer



Individual Workstation



FIG. 19

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.